



014

Date

12/03/2021

Legend

A Attention required  
√ In order  
- Not applicable

Name  
**Shannons**  
Address  
40 CORPORATE DRIVE  
HEATHERTON  
VICTORIA, 3202

PHONE: 134646

143

Vehicle make and model

MERCEDES BENZ 280 SL

Body Style

CONVERTIBLE

Year

1970

Registration

Odometer

18429

VIN

11304422018456 I/D PLATE

Summary of overall condition of vehicle

GOOD

FAIR

POOR

Comments:

6 CYLINDER FUEL INJECTED / AUTO  
DRIVABILITY AND PERFORMANCE TEST

Engine/Exhaust

Engine Oil Condition

Engine Noises

Air Filter

Fuel System

Water Pump

Exhaust Condition

Oil Leaks

Tune Condition

Drive Belts

Fuel Leaks

Coolant

Exhaust Mounts

Engine Mounts

Smoke

Emission system

Radiator/Hoses

Thermostat

Exhaust leaks

Comments:

Transmission/Driveline

AUTOMATIC

MANUAL

Transmission

Shift Operation

Noises

Clutch OPS

Linkages

Drive shaft/ Boots

Oil/Fluid Condition

Mounts

Inhibitor Switch

Adjustment

CV/Universal joints

Final Drive

Comments:

AUTO TRANSMISSION FLUID LEAK  
DIFFERENTIAL OIL LEAK

Steering/Suspension

Power Assistance

YES

NO

Steering Box/Rack

Steering linkage

Shock Absorbers

Bushes/Pivots

Tyre Wear

Wheel/ Spare

Oil Leaks

Power Steering

Springs

Wheel Bearings

Tyre Condition

Driveability

Comments:

Brakes

Operation

Pads/lining

Pedal Height

Electrical

Wiring

Indicators

Battery

Park brake

Line Condition

Pedal Rubbers

Headlights/Aim

Instrumentation

Charge Rate

Fluid leaks

Hose Condition

ABS check light

Exterior Lighting

Windscreen Wipers

Horn

Comments:

WINDSCREEN WIPERS SWITCH BROKEN  
REVERSE LIGHTS AND LEFT HAND HEADLIGHT INOPERATIVE

Body

Structure

Panel condition

Previous Repairs

Door/Window op

Door Locks

Seat Belts

Corrosion

Paint Condition

Windscreen/glass

Windows Tinting

Seats and Trim

Door handles

Comments:

LEFT HAND FLOOR PAN AND SUB RAIL DENTED. REAR LEFT HAND RAIL HAVE RUST REPAIRS. FRONT SCUTTLE RUST AND WHEEL HOUSING BRACES. UNDERSIDE SURFACE RUST WEEPING THROUGH BODY DEADENER. VARIOUS CABIN PANELS SURFACE RUST - FLOOR PAN AND RH SCUTTLE. HAS FRONT PANEL ACCIDENT DAMAGE REPAIRS. RAIL INNER BOX SECTIONS SURFACE RUSTING. FRONT RAILS AND TIE BAR SURFACE RUSTING AND HAVE RUST AND REPAIRS

Miscellaneous

Demister

Air conditioner

Heater

LPG Compliance

Ability to run on  
Alternative Fuels

Other

Comments:

HEATER CONTROLS INOPERATIVE. CABIN CLOCK INOPERATIVE  
PETROL TANK HAVE FIBREGLASS REPAIRS

## **ACCREDITED PREPURCHASE INPECTION REPORT TERMS AND CONDITIONS**

Pre-purchase inspection reports are based on a visual inspection of the condition of the specific items set out in this report form.

Neither Shannons nor Sangate service company pty ltd will be responsible for any defects that could reasonably be expected to have become evident by the dismantling or removal of parts of the vehicle or by inspection of any items not set out in the report form.

Supplementary restraint or air bag systems have been specifically excluded from this test due to the complexity of test procedures. Customers who are considering the purchase of a vehicle fitted with an srs or air bag system are advised to refer the vehicle to an authorized service agent for system functionality.

The pre – purchase inspection report is not substitute for a roadworthy test, which is a tolerance test. The customer acknowledges that receipt of a satisfactory condition report does not mean the vehicle will also pass a roadworthy test.

Sangate will not be held liable for

- a) Carrying out pre-purchase or any services connected with such inspections: or
- b) Providing to any person any information in connection with a pre-purchase vehicle inspection including this report form.

To the extent permissible under the Trade Practices Act and any other act of Parliament, the liability of Sangate for any loss or damage to the vehicle for:

- a) Any breach of any term, condition or warranty implied by such legislation shall be limited to the supply of the service and shall be equivalent to the cost if having the service supplied; and
- b) Any breach of contract or statute or any tort by Sangate shall be limited to an amount equal to the pre- purchase inspection fee paid.