



Pre-Purchase Inspection Report

Report No.

SR - 121

Date

14-01-2010

Shannons Corporation Pty Ltd Sydney

Legend

G	Good	X	Attention Required
F	Fair	√	In Satisfactory Order
P	Poor	-	Not Applicable

Vehicle Make and Model

LINCOLN CONTINENTAL MK 5

Body Style

2 DOOR

Year Registration Odometer - Mls/Km

1977 YFE70D 63175

VIN

7Y89A859979

Summary of overall condition of vehicle Good Fair Poor

Comments: VEHICLE IN EXCELLENT CONDITION

Engine/Exhaust

<input checked="" type="checkbox"/> <input type="checkbox"/> G Engine Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G Engine Noises	<input checked="" type="checkbox"/> <input type="checkbox"/> G Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> G Fuel System	<input checked="" type="checkbox"/> <input type="checkbox"/> G Water Pump	<input checked="" type="checkbox"/> <input type="checkbox"/> G Exhaust Condition
<input checked="" type="checkbox"/> <input type="checkbox"/> G Oil Leaks	<input checked="" type="checkbox"/> <input type="checkbox"/> G Tune Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G Drive Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> G Fuel Leaks	<input checked="" type="checkbox"/> <input type="checkbox"/> F Coolant	<input checked="" type="checkbox"/> <input type="checkbox"/> G Exhaust Mounts
<input checked="" type="checkbox"/> <input type="checkbox"/> G Engine Mounts	<input checked="" type="checkbox"/> <input type="checkbox"/> G Smoke	<input checked="" type="checkbox"/> <input type="checkbox"/> G Emission System	<input checked="" type="checkbox"/> <input type="checkbox"/> G Radiator/Hoses	<input checked="" type="checkbox"/> <input type="checkbox"/> G Thermostat	<input checked="" type="checkbox"/> <input type="checkbox"/> G Exhaust Leaks

Comments: MINOR ENGINE OIL LEAK

Transmission/Driveline Automatic Manual

<input checked="" type="checkbox"/> <input type="checkbox"/> G Transmission	<input checked="" type="checkbox"/> <input type="checkbox"/> G Shift Operation	<input checked="" type="checkbox"/> <input type="checkbox"/> G Noises	<input type="checkbox"/> <input type="checkbox"/> - Clutch OPS	<input checked="" type="checkbox"/> <input type="checkbox"/> G Linkages	<input checked="" type="checkbox"/> <input type="checkbox"/> G Driveshaft/Boots
<input checked="" type="checkbox"/> <input type="checkbox"/> G Oil/Fluid Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G Mounts	<input checked="" type="checkbox"/> <input type="checkbox"/> G Inhibitor Switch	<input type="checkbox"/> <input type="checkbox"/> - Adjustment	<input checked="" type="checkbox"/> <input type="checkbox"/> G CV/Universal Joints	<input checked="" type="checkbox"/> <input type="checkbox"/> G Final Drive Unit

Comments: MINOR FLUID LEAKS FROM TRANSMISSION & FINAL DRIVE UNIT

Steering/Suspension Power Assistance Yes No

<input checked="" type="checkbox"/> <input type="checkbox"/> G Steering Box/Rack	<input checked="" type="checkbox"/> <input type="checkbox"/> G Steering Linkage	<input checked="" type="checkbox"/> <input type="checkbox"/> G Shock Absorbers	<input checked="" type="checkbox"/> <input type="checkbox"/> G Bushes/Pivots	<input checked="" type="checkbox"/> <input type="checkbox"/> G Tyre Wear	<input checked="" type="checkbox"/> <input type="checkbox"/> G Wheels/Spare
<input checked="" type="checkbox"/> <input type="checkbox"/> G Oil Leaks	<input checked="" type="checkbox"/> <input type="checkbox"/> G Power Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> G Road Springs	<input checked="" type="checkbox"/> <input type="checkbox"/> G Wheel Bearings	<input checked="" type="checkbox"/> <input type="checkbox"/> G Tyre Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G Driveability

Comments:

Brakes Hydraulics/ABS

<input checked="" type="checkbox"/> <input type="checkbox"/> G Operation	<input checked="" type="checkbox"/> <input type="checkbox"/> G Pads/Lining	<input checked="" type="checkbox"/> <input type="checkbox"/> G Pedal Height	Electrical	<input checked="" type="checkbox"/> <input type="checkbox"/> G Wiring	<input checked="" type="checkbox"/> <input type="checkbox"/> G Indicators	<input checked="" type="checkbox"/> <input type="checkbox"/> G Battery
<input checked="" type="checkbox"/> <input type="checkbox"/> G Park/Hand Brake	<input checked="" type="checkbox"/> <input type="checkbox"/> G Line Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G Pedal Rubbers	<input checked="" type="checkbox"/> <input type="checkbox"/> G Headlights/Aim	<input checked="" type="checkbox"/> <input type="checkbox"/> G Instrumentation	<input checked="" type="checkbox"/> <input type="checkbox"/> G Charge Rate	
<input checked="" type="checkbox"/> <input type="checkbox"/> G Fluid Leaks	<input checked="" type="checkbox"/> <input type="checkbox"/> G Hose Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G ABS/Warning Light	<input checked="" type="checkbox"/> <input type="checkbox"/> G Exterior Lighting	<input checked="" type="checkbox"/> <input type="checkbox"/> G Windscreen Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> G Horn	

Comments:

Body

<input checked="" type="checkbox"/> <input type="checkbox"/> G Structure	<input checked="" type="checkbox"/> <input type="checkbox"/> G Panel Condition	<input type="checkbox"/> <input type="checkbox"/> - Previous Repairs	<input checked="" type="checkbox"/> <input type="checkbox"/> G Door & Window Operation	<input checked="" type="checkbox"/> <input type="checkbox"/> G Door Locks	<input checked="" type="checkbox"/> <input type="checkbox"/> G Seat Belts
<input checked="" type="checkbox"/> <input type="checkbox"/> G Corrosion	<input checked="" type="checkbox"/> <input type="checkbox"/> G Paint Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> G Windscreen/Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> G Window tinting	<input checked="" type="checkbox"/> <input type="checkbox"/> G Seats and Trim	<input checked="" type="checkbox"/> <input type="checkbox"/> G Door Handles

Comments:

Miscellaneous

<input checked="" type="checkbox"/> <input type="checkbox"/> G 'Demister	<input checked="" type="checkbox"/> <input type="checkbox"/> G Air Conditioner	<input checked="" type="checkbox"/> <input type="checkbox"/> G Heater	<input type="checkbox"/> <input type="checkbox"/> - LPG Compliance	<input type="checkbox"/> <input type="checkbox"/> - Ability to run on alternative fuels	<input type="checkbox"/> <input type="checkbox"/> - Other
--	--	---	--	---	---

Specialists in Prestige
Automotive Service

RANGE ROVER - DISCOVERY
JAGUAR - LOTUS
CITROEN - MORGAN



Unit 1-39 Hotham Parade
ARTARMON NSW 2064

Ph: 02 9906 5266
Fax: 02 9906 6250
Service@cremorneprestige.com.au

Vehicle Inspection Report **Shannon's Auctions**

*For your information
Process for this report*

What is inspected:

This report is based on a visual inspection to the main areas of the vehicle only.
A road test is carried out on the vehicle if roadworthy.

Boxed codes are entered to give an indication on what repairs may be necessary and the level of repair required. It is also an indication of the vehicles overall condition.

We have not removed any part of the vehicle for this inspection.
The underside of vehicle is inspected on a vehicle hoist.
The road test, if conducted, is done within the immediate area of our workshop and done within the local speed limits.

What is not inspected on the vehicle:

Engine compressions
Engine cam/timing belts
Fluid levels and quality of fluid - unless stated elsewhere in this report
Source of oil leaks - unless stated elsewhere in this report
Audio system sound and reception quality

Disclaimer:

Cremorne Prestige Service Pty Ltd, it's Management, Inspectors and Staff will not be held liable or responsible for any claim whatsoever in relation to this report and/or to your decision to purchase the vehicle. This report is done on a visual basis only.

We would advise a second opinion on the vehicle if you feel it necessary.