



# VEHICLE APPRAISAL REPORT

## Shannons Auctions Ltd

**AUTOMOTIVE SOLUTIONS**

DATE: 8 APRIL 2008

LOT NO:

**VEHICLE DETAILS**

MAKE: LEYLAND  
 BODY TYPE: RAODSTER  
 REG: KS-158  
 ENG. NO: 18GGRWB1124067

MODEL: MG  
 YEAR: 1971  
 ODOMETER: 65,965  Klms  Miles  
 VIN NO: YHN91482

Engine Number sighted:  Yes  No

Vin Number sighted:  Yes  No

ENGINE CAPACITY: 4 CYLINDER  
 PAINT COLOR: RED

TRANSMISSION TYPE: MANUAL  
 INTERIOR TYPE/COLOR: BLACK

Options:  P/S  A/C  E/W  C/L  C/C  SNRF  ABS  Tow Bar Other \_\_\_\_\_

**Body Section**

| Condition:                   | GOOD                                | FAIR                     | POOR                     | N/A                      | Comments |
|------------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|----------|
| Condition of Panels          | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Condition of Paint           | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Panel Alignment              | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Underbody / Undercarriage    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Chrome / Bumpers / Stainless | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Rubbers / Seals / Felts      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Windows / Lights / Lenses    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Engine Bay Presentation      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Boot / Tray Presentation     | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |

Minor defects and panel repairs of a satisfactory nature may not be recorded

**Body Section Notes:**

|                              |                              |
|------------------------------|------------------------------|
| Visible Body Repairs         | ➤                            |
| Ripples                      | ➤ <i>EVIDENT IN LHF DOOR</i> |
| Cosmetic Repairs & Touch Ups | ➤                            |
| Dents                        | ➤                            |
| Small Dents                  | ➤                            |
| Paint Defects                | ➤                            |
| Stone Chips                  | ➤                            |
| Rust                         | ➤                            |
| Scratches                    | ➤                            |

**Interior Section:**

| Condition:                   | GOOD                                | FAIR                     | POOR                     | N/A                      | Comments |
|------------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|----------|
| Seats / Carpets / Rooflining | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Dash / Steering Wheel / Trim | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |

**ANY CAR.**

**ANY STATE.**

**ANYTIME!**

VIP Automotive Solutions

A.C.N. 125 721 511 A.B.N. 20 125 721 511

PO Box 10, Pascoe Vale South. Victoria. 3044 Ph: 0500 555 227 Fax: (03) 9304 3377 [www.vipinspections.com](http://www.vipinspections.com) Email: [vipmail@bigpond.com](mailto:vipmail@bigpond.com)



# VEHICLE APPRAISAL REPORT

## Shannons Auctions Ltd

**AUTOMOTIVE SOLUTIONS**

LOT NO:

**Drivetrain:**

| Condition:                     | GOOD                                | FAIR                     | POOR                     | N/A                      | Comments                   |
|--------------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|----------------------------|
| Fluids / Levels                | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Fanbelts / Hoses / Mounts      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Electrical Components & System | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Steering/Suspension Components | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Brake System                   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Cooling System                 | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Fuel & Exhaust Systems         | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤                          |
| Wheels / Tyres / Hubcaps       | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤ <b>TYRE PRESSURE LOW</b> |

**Engine:**

*(All engine tests based after a 15 minute warm up period)*

| Condition:                 | GOOD                                | FAIR                     | POOR                     | N/A                      | Comments |
|----------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|----------|
| Cold engine start          | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Warm Engine Runs           | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |
| Temp / Oil / Fuel Readings | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | ➤        |

**Fluid & Emission Leaks:**

- Upper Engine     Lower Engine     Gearbox/Trans     Differential Axle     Steering Component     Brake System  
 Cooling System     Fuel System     Suspension System     Exhaust System     Turbo Charger     Other

**Nature of Leaks:**

- None Evident     Minor     Moderate     Major     Recently Steam Cleaned

**Engine / Drivetrain Requires:**

- Tune/service     Repairs / Adjustments

**Roadtest:**

**2 km roadtest subject to road laws, the vehicle being registered and/or driven on a trade plate, and considered in a safe driveable condition.**

| Assessment of:              | GOOD                                | FAIR                                | POOR                     | N/A                                 | Comments                      |
|-----------------------------|-------------------------------------|-------------------------------------|--------------------------|-------------------------------------|-------------------------------|
| Ride / Handling             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | ➤                             |
| Steering / Braking          | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | ➤ <b>TRACKS A LITTLE LEFT</b> |
| Engine Response             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | ➤                             |
| Shift Patterns (Automatic)  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> | ➤                             |
| Clutch / Gearshift (Manual) | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | ➤                             |
| Air Conditioner / Heater    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | ➤                             |

- Detection of:**     Rattles / Squeaks     Vibration / Shudder     Drivetrain Noises     Strange Noises     Wind noises  
 Other \_\_\_\_\_

**Speed limit on Roadtest:**

- 50kph / 30mph     60kph / 40mph     70kph / 45mph     80kph / 50 mph     100kph / 60mph

**Roadtest comments:**

- **DRIVES NICE, STEERING TRACKS A LITTLE TO THE LEFT, TYRE PRESSURES WERE LOW**  
 ➤

**Summary:**

- This vehicle is a     Very Good     Good     Fair     Poor example of this fine marque.  
 It drives in     Very Good     Good     Fair     Poor condition for its age     Not tested  
 It will require     Regular Maintenance     Some Repairs & Adjustments     Extensive Repairs/Restoration to maintain  
 to maintain this vehicle in a safe, reliable and presentable condition

**Items requiring attention:**

- **OIL LEAK, INDICATOR STORK NEEDS SECURING, INDICATORS NOT SELF-CANCELLING, WHEEL ALIGNMENT REQ.**

**ANY CAR.**

**ANY STATE.**

**ANYTIME!**

VIP Automotive Solutions  
 A.C.N. 125 721 511 A.B.N. 20 125 721 511  
 PO Box 10, Pascoe Vale South. Victoria. 3044    Ph: 0500 555 227    Fax: (03) 9304 3377    [www.vipinspections.com](http://www.vipinspections.com)    Email: [vipmail@bigpond.com](mailto:vipmail@bigpond.com)

This report is not a guarantee that the items checked during the inspection will continue to function after the inspection.

A copy of our Disclaimer is available.

This report is **NOT** a recommendation to purchase the fore-mentioned vehicle. This decision rests wholly and solely on **YOU** the buyer.