



# VEHICLE APPRAISAL REPORT

## Shannons Auctions Ltd

**AUTOMOTIVE SOLUTIONS**

DATE: 19 APRIL 08

LOT NO:  

**VEHICLE DETAILS**

MAKE: CHEVROLET  
 BODY TYPE: COUPE  
 REG: NOT REG  
 ENG. NO: 18-314386 T1108EE

MODEL: CAMARO  
 YEAR: 1968  
 ODOMETER: 02,419  Klms  Miles  
 VIN NO: 58124378L314386

Engine Number sighted:  Yes  No

Vin Number sighted:  Yes  No

ENGINE CAPACITY: 327 CID V8  
 PAINT COLOR: BLUE

TRANSMISSION TYPE: AUTOMATIC  
 INTERIOR TYPE/COLOR: BLACK

Options:  P/S  A/C  E/W  C/L  C/C  SNRF  ABS  Tow Bar Other     

**Body Section**

Condition:	GOOD	FAIR	POOR	N/A	Comments
Condition of Panels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Condition of Paint	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Panel Alignment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Underbody / Undercarriage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Chrome / Bumpers / Stainless	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Rubbers / Seals / Felts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Windows / Lights / Lenses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Engine Bay Presentation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ <span style="color: blue;">FLUID SPILL UNDER BATTERY</span>
Boot / Tray Presentation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

Minor defects and panel repairs of a satisfactory nature may not be recorded

**Body Section Notes:**

Visible Body Repairs	➤
Ripples	➤
Cosmetic Repairs & Touch Ups	➤
Dents	➤
Small Dents	➤
Paint Defects	➤ <span style="color: blue;">EVIDENT ON RHD FENDER AND RHR C PILLAR (PAINT BLISTERING)</span>
Stone Chips	➤
Rust	➤
Scratches	➤

**Interior Section:**

Condition:	GOOD	FAIR	POOR	N/A	Comments
Seats / Carpets / Rooflining	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Dash / Steering Wheel / Trim	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

**ANY CAR.**

**ANY STATE.**

**ANYTIME!**

VIP Automotive Solutions

A.C.N. 125 721 511 A.B.N. 20 125 721 511

PO Box 10, Pascoe Vale South. Victoria. 3044 Ph: 0500 555 227 Fax: (03) 9304 3377 [www.vipinspections.com](http://www.vipinspections.com) Email: [vipmail@bigpond.com](mailto:vipmail@bigpond.com)



# VEHICLE APPRAISAL REPORT

## Shannons Auctions Ltd

**AUTOMOTIVE SOLUTIONS**

LOT NO:

**Drivetrain:**

Condition:	GOOD	FAIR	POOR	N/A	Comments
Fluids / Levels	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Fanbelts / Hoses / Mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Electrical Components & System	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ <b>WASHER EMPTY</b>
Steering/Suspension Components	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Brake System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Fuel & Exhaust Systems	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Wheels / Tyres / Hubcaps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

**Engine:**

*(All engine tests based after a 15 minute warm up period)*

Condition:	GOOD	FAIR	POOR	N/A	Comments
Cold engine start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Warm Engine Runs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ <b>SLIGHT MISFIRE ON THROTTLE</b>
Temp / Oil / Fuel Readings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

**Fluid & Emission Leaks:**

- Upper Engine     Lower Engine     Gearbox/Trans     Differential Axle     Steering Component     Brake System  
 Cooling System     Fuel System     Suspension System     Exhaust System     Turbo Charger     Other \_\_\_\_\_

**Nature of Leaks:**

- None Evident     Minor     Moderate     Major     Recently Steam Cleaned

**Engine / Drivetrain Requires:**

- Tune/service     Repairs / Adjustments

**Roadtest:**

**2 km roadtest subject to road laws, the vehicle being registered and/or driven on a trade plate, and considered in a safe driveable condition.**

Assessment of:	GOOD	FAIR	POOR	N/A	Comments
Ride / Handling	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ <b>FIRM BUMPY RIDE</b>
Steering / Braking	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Engine Response	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ <b>MISFIRE ON KICKDOWN</b>
Shift Patterns (Automatic)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Clutch / Gearshift (Manual)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	➤
Air Conditioner / Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

- Detection of:**     Rattles / Squeaks     Vibration / Shudder     Drivetrain Noises     Strange Noises     Wind noises  
 Other \_\_\_\_\_

**Speed limit on Roadtest:**

- 50kph / 30mph     60kph / 40mph     70kph / 45mph     80kph / 50 mph     100kph / 60mph

**Roadtest comments:**

➤  
 ➤

**Summary:**

- This vehicle is a     Very Good     Good     Fair     Poor example of this fine marque.  
 It drives in     Very Good     Good     Fair     Poor condition for its age     Not tested  
 It will require     Regular Maintenance     Some Repairs & Adjustments     Extensive Repairs/Restoration to maintain  
 to maintain this vehicle in a safe, reliable and presentable condition

**Items requiring attention:**

➤ **ENGINE REQUIRES TUNE TO ELIMINATE MISFIRE**  
 ➤

**ANY CAR.**

**ANY STATE.**

**ANYTIME!**

VIP Automotive Solutions  
 A.C.N. 125 721 511 A.B.N. 20 125 721 511  
 PO Box 10, Pascoe Vale South, Victoria. 3044    Ph: 0500 555 227    Fax: (03) 9304 3377    [www.vipinspections.com](http://www.vipinspections.com)    Email: [vipmail@bigpond.com](mailto:vipmail@bigpond.com)

This report is not a guarantee that the items checked during the inspection will continue to function after the inspection.

A copy of our Disclaimer is available.

This report is **NOT** a recommendation to purchase the fore-mentioned vehicle. This decision rests wholly and solely on **YOU** the buyer.