



VEHICLE APPRAISAL REPORT

Shannons Auctions Ltd

AUTOMOTIVE SOLUTIONS

DATE: 7 APRIL 2008

LOT NO:

VEHICLE DETAILS

MAKE: COBRA
 BODY TYPE: ROADSTER
 REG: EE-427
 ENG. NO: OYC41071

MODEL: DRB
 YEAR: 1998
 ODOMETER: 23,727 Klms Miles
 VIN NO: 6R9P01000W1KJ9001

Engine Number sighted: Yes No

Vin Number sighted: Yes No

ENGINE CAPACITY: WINDSOR V8
 PAINT COLOR: PURPLE & SILVER METALLIC

TRANSMISSION TYPE: MANUAL
 INTERIOR TYPE/COLOR: GREY

Options: P/S A/C E/W C/L C/C SNRF ABS Tow Bar Other _____

Body Section

Condition:	GOOD	FAIR	POOR	N/A	Comments
Condition of Panels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Condition of Paint	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ FEW MINOR SCUFFS + BLEMISHES
Panel Alignment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ RHF DOOR REQUIRES ADJUSTMENT
Underbody / Undercarriage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Chrome / Bumpers / Stainless	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Rubbers / Seals / Felts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Windows / Lights / Lenses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Engine Bay Presentation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Boot / Tray Presentation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

Minor defects and panel repairs of a satisfactory nature may not be recorded

Body Section Notes:

Visible Body Repairs	➤
Ripples	➤
Cosmetic Repairs & Touch Ups	➤
Dents	➤
Small Dents	➤
Paint Defects	➤
Stone Chips	➤ SMALL CHIP ON LHR QUARTER PANEL
Rust	➤
Scratches	➤

Interior Section:

Condition:	GOOD	FAIR	POOR	N/A	Comments
Seats / Carpets / Rooflining	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Dash / Steering Wheel / Trim	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

ANY CAR.

ANY STATE.

ANYTIME!

VIP Automotive Solutions

A.C.N. 125 721 511 A.B.N. 20 125 721 511

PO Box 10, Pascoe Vale South. Victoria. 3044 Ph: 0500 555 227 Fax: (03) 9304 3377 www.vipinspections.com Email: vipmail@bigpond.com



VEHICLE APPRAISAL REPORT

Shannons Auctions Ltd

AUTOMOTIVE SOLUTIONS

LOT NO:

Drivetrain:

Condition:	GOOD	FAIR	POOR	N/A	Comments
Fluids / Levels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Fanbelts / Hoses / Mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Electrical Components & System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Steering/Suspension Components	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Brake System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Fuel & Exhaust Systems	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Wheels / Tyres / Hubcaps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

Engine:

(All engine tests based after a 15 minute warm up period)

Condition:	GOOD	FAIR	POOR	N/A	Comments
Cold engine start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Warm Engine Runs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Temp / Oil / Fuel Readings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤

Fluid & Emission Leaks:

- Upper Engine Lower Engine Gearbox/Trans Differential Axle Steering Component Brake System
 Cooling System Fuel System Suspension System Exhaust System Turbo Charger Other

Nature of Leaks:

- None Evident Minor Moderate Major Recently Steam Cleaned

Engine / Drivetrain Requires:

- Tune/service Repairs / Adjustments

Roadtest:

2 km roadtest subject to road laws, the vehicle being registered and/or driven on a trade plate, and considered in a safe driveable condition.

Assessment of:	GOOD	FAIR	POOR	N/A	Comments
Ride / Handling	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Steering / Braking	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤ BRAKES ARE SPONGY
Engine Response	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Shift Patterns (Automatic)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	➤
Clutch / Gearshift (Manual)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	➤
Air Conditioner / Heater	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	➤

- Detection of:** Rattles / Squeaks Vibration / Shudder Drivetrain Noises Strange Noises Wind noises
 Other _____

Speed limit on Roadtest:

- 50kph / 30mph 60kph / 40mph 70kph / 45mph 80kph / 50 mph 100kph / 60mph

Roadtest comments:

➤ **DRIVES OKAY, BRAKES ARE SPONGY YET STOP WELL.**

➤

Summary:

This vehicle is a Very Good Good Fair Poor example of this fine marque.
 It drives in Very Good Good Fair Poor condition for its age Not tested
 It will require Regular Maintenance Some Repairs & Adjustments Extensive Repairs/Restoration to maintain
 to maintain this vehicle in a safe, reliable and presentable condition

Items requiring attention:

➤ **OIL LEAKS, ADJUST RHF DOOR, ADJUST HANDBRAKE**

ANY CAR.

ANY STATE.

ANYTIME!

VIP Automotive Solutions
 A.C.N. 125 721 511 A.B.N. 20 125 721 511
 PO Box 10, Pascoe Vale South. Victoria. 3044 Ph: 0500 555 227 Fax: (03) 9304 3377 www.vipinspections.com Email: vipmail@bigpond.com

This report is not a guarantee that the items checked during the inspection will continue to function after the inspection.

A copy of our Disclaimer is available.

This report is **NOT** a recommendation to purchase the fore-mentioned vehicle. This decision rests wholly and solely on **YOU** the buyer.