

Pre-Purchase Inspection

Report No

Classic Automobilia

0425 250 613

Maintenance, Modifications & Restorations

Auction Lot No
134

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
9/03/2021	Mazda RX7 Spirit R	2002	71,073km	6U90000FD35606437

Overall Rating	Comments
	Very well presented example.

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	✓					
Glass	✓					
Bodywork	✓					
Paintwork	✓					A couple of very small dings, scuffs on R/H sill and spoiler lip.
Lamps Condition	✓					
Bumper Bars	✓					
Brightwork	✓					
Seals	✓					
Convertible Roof					✓	

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area	✓					
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim	✓					
Doors	✓					
Windows and Mirrors	✓					
Heating and Ventilation	✓					
Lights/Wipers/Washers/Horn	✓					
Other Electrical	✓					
Entertainment Equipment	✓					
ABS/SRS	✓					

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓					
Corrosion	✓					Underbody spoilt by black painting of subframes, diff and fuel tank.
Powertrain	✓					
Exhaust	✓					
Brakes	✓					
Wheels & Tyres	✓					
Steering & Suspension	✓					
Fuel System	✓					
Fluid Leaks	✓					

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	✓					
Fluid Levels/Condition	✓					
Cooling System	✓					
Power Steering	✓					
Electrical	✓					
Engine Running	✓					
Air Conditioning	✓					

ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓						
Transmission	✓						
Noise and Vibration	✓						Transmission a bit noisy.
Steering and Suspension	✓						
Braking	✓						
Clutch	✓						
Instruments	✓						

General Comments

Key	
Good	Operational or well presented at time of inspection
Fair	Commensurate for age of vehicle but has wear and tear
Repair	Requires repair, replacement or refurbishment
Wetting	Fluid escaping with the potential to drip
Leaking	Fluid escaping and dripping
U/S	Unservicable
N/S	Not secure
N/W	Not working
N/A	Not Applicable
N/C	Not checked
★ ☆ ☆ ☆ ☆	Vehicle requires substantial work or restoration
★ ★ ☆ ☆ ☆	Vehicle is in poor condition and in need of TLC
★ ★ ★ ☆ ☆	Vehicle is commensurate with age and useable
★ ★ ★ ★ ☆	Vehicle is in very good condition
★ ★ ★ ★ ★	Vehicle is in excellent condition

Disclaimer

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.

This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.