

Pre Purchase Inspection Report

(this report is subject to the terms and conditions on the reverse of this form)

Name SHANNONS AUCTIONS		Phone 	Legend Needs attention = A In order = ✓ Not applicable = na	Stock No.
Address 40 CORPORATE DRIVE HEATHERTON				Date 2/04/2022
Vehicle make and model BENTLEY SEDAN BLACK				Report No.
Year 1954	Registration NO REG	Odometer 73750	VIN B007702	Body style SEDAN
Overall condition of vehicle <input type="checkbox"/> Good			<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Poor
Comments:				

<input checked="" type="checkbox"/> Oil condition	<input checked="" type="checkbox"/> Engine noise	<input checked="" type="checkbox"/> Air filter	<input checked="" type="checkbox"/> Fuel system	<input checked="" type="checkbox"/> Water pump	<input checked="" type="checkbox"/> Exhaust condition
A Oil leaks	<input checked="" type="checkbox"/> Tune condition	<input checked="" type="checkbox"/> Drive belts	<input checked="" type="checkbox"/> Fuel leaks	<input checked="" type="checkbox"/> Coolant	<input checked="" type="checkbox"/> Exhaust mounts
<input checked="" type="checkbox"/> Engine mounts	<input checked="" type="checkbox"/> Smoke	na Emission system	<input checked="" type="checkbox"/> Radiator/hoses	<input checked="" type="checkbox"/> Thermostat	<input checked="" type="checkbox"/> Exhaust leaks
Comments: SMALL AMOUNT OF OIL LEAKING AROUND ENGINE SUMP AREA.					

Transmission/Driveline		Manual			
A Transmission	<input checked="" type="checkbox"/> Shift operation	<input checked="" type="checkbox"/> Noise	na Clutch operation	<input checked="" type="checkbox"/> Linkages	<input checked="" type="checkbox"/> Drive shaft boots
<input checked="" type="checkbox"/> Oil/fluid condition	<input checked="" type="checkbox"/> Mounts	<input checked="" type="checkbox"/> Inhibitor switch	<input checked="" type="checkbox"/> Adjustments	<input checked="" type="checkbox"/> CV/universal joints	A Final drive
Comments: OIL LEAK REAR OF TRANSMISSION AND DIFF HOUSING PINION SEAL AREA.					

Steering/Suspension					
<input checked="" type="checkbox"/> Steering box/rack	<input checked="" type="checkbox"/> Steering linkage	A Shock Absorbers	A Bushes/pivots	<input checked="" type="checkbox"/> Tyre wear	<input checked="" type="checkbox"/> Wheel/spare
<input checked="" type="checkbox"/> Oil leaks	<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Springs	<input checked="" type="checkbox"/> Wheel bearings	<input checked="" type="checkbox"/> Tyre condition	<input checked="" type="checkbox"/> Driveability
Comments: REAR DAMPERS LEAKING OIL, BUMP STOPS BROKEN AND ONE MISSING.					

Brakes			Electrical		
A Operation	A Pads/linings	<input checked="" type="checkbox"/> Pedal feel	<input checked="" type="checkbox"/> Wiring	<input checked="" type="checkbox"/> Indicators	<input checked="" type="checkbox"/> Battery
<input checked="" type="checkbox"/> Park brake	<input checked="" type="checkbox"/> Line condition	<input checked="" type="checkbox"/> Pedal rubbers	<input checked="" type="checkbox"/> Headlights/aim	<input checked="" type="checkbox"/> Instrumentation	<input checked="" type="checkbox"/> Charge rate
<input checked="" type="checkbox"/> Fluid leaks	<input checked="" type="checkbox"/> Hose condition	na ABS check light	<input checked="" type="checkbox"/> Exterior lighting	<input checked="" type="checkbox"/> Windscreen wipers	<input checked="" type="checkbox"/> Horn
Comments: BRAKE SYSTEM REQUIRES ATTENTION, FRICTION PLATES GRINDING ON SLOW SPEED BRAKING.					

Body					
A Structure	A Panel condition	<input checked="" type="checkbox"/> Previous repairs	<input checked="" type="checkbox"/> Door/window ops	<input checked="" type="checkbox"/> Door locks	<input checked="" type="checkbox"/> Seat belts
A Corrosion	A Paint condition	<input checked="" type="checkbox"/> Windscreen/glass	na Window tint	<input checked="" type="checkbox"/> Seats/trim	<input checked="" type="checkbox"/> Door handles
Comments: SMALL RUST HOLES IN REAR OF BOOT FLOOR AND LEFT REAR INNER QUARTER PANEL, PAINT AND PANEL IMPERFECTIONS ON ALL PANELS.					

Miscellaneous					
<input checked="" type="checkbox"/> Demister	<input checked="" type="checkbox"/> Air conditioner	<input checked="" type="checkbox"/> Heater	na LPG compliance	na LPG running	na Other
na Convertible top - Condition		na Convertible top - operation			
Comments: DRIVES OK					

Vehicle inspection disclaimer

This vehicle inspection report is based on largely a visual inspection. It is not practical to dismantle every item on the vehicle for inspection.

This inspection is prepared for Shannons Auctions and no warranty is offered or provided, nor is equivalent or a substitute of a roadworthy certificate. The report may indicate a problem or problems but not provide any further details into the problem, this is because further dismantling may be required to provide accurate diagnosis. Whilst every care is taken, EuroCars Road and Track Pty Ltd cannot report on a defect that the inspector cannot see or does not appear during inspection.

EuroCars Road and Track or Shannons will not be held responsible for defects that may have been-disguised in order to deceive the agent/s or potential buyers.

EuroCars Road and Track do not check every item, items that are excluded (but not limited to) include; timing belts / chains, security system, entertainment systems including cassette/compact disc players, etc.

We do not take any responsibility for the verification or authentication of the vehicle; this is solely the responsibility of the purchaser. VIN, Chassis and Engine numbers are checked however not guaranteed.

It is recommended to refer any vehicle with a supplementary restraint or air bag system to an authorised agent for inspection. EuroCars will not be held liable for any change in condition or damage after initial inspection.