FORM 11: AUCTION NOTICE (Dealer to tick applicable statement(s) from below):			
Motor Dealers and Repairers Act 2013: Section 57 and 72. LOT 157: 17 th – 24 th MAY22 ONLINE Timed Auction			
VEHICLE INFORMATION			
Make:	1955 BENTLEY	VIN/Chassis number:	B18YD
Model:	R-Type Saloon	Registration Number:	XC244
~	This vehicle does not come with a dealer guarantee under the Motor Dealers and Repairers Act 2013.		
This vehicle is being sold by an auction conducted by the dealer as agent or consignee for the vendor. The dealer does not own the			
vehicle. By purchasing this vehicle by auction it has no dealer guarantee under the Motor Dealers and Repairers Act 2013. The dealer is			
not required to repair or make good any defect which may exist or occur in this vehicle. The dealer must give to the purchaser on			
delivery of the vehicle, a current inspection report.			
	This vehicle does not come with consumer guarantees under the Australian Consumer Law.		
This vehicle is being sold by an auction conducted by the dealer as agent for the vendor. The dealer does not own the vehicle. By			
purchasing this vehicle by auction it has no consumer guarantee under the Australian Consumer Law.			
	This vehicle comes with consumer guarantees under the Australian Consumer Law.		
This vehicle is being sold by an auction conducted by the motor dealer who owns the motor vehicle. By purchasing this vehicle by			
auction a consumer guarantee as to the acceptable quality of this vehicle is provided under the Australian Consumer Law. In the event			
of a failure to comply with the consumer guarantee, the purchaser's right to any remedy will depend on whether the failure is related			
to a major or minor problem with the vehicle sold.			
Minor problem: where the vehicle purchased can usually be put right within a reasonable timeframe, the dealer can choose between a			
refund of the purchase price, a replacement of the vehicle or repair of the vehicle.			
Major problem: the purchaser can choose between a refund of the purchase price, a replacement of the vehicle or repair of the			
vehicle			