

L&D Automotive

Kelvin Grove Steering Specialists

17 Bishop St, Kelvin Grove, QLD 4059

David Blee

All mechanical repairs & servicing

Wheel alignment & balancing

Tel: 07 3352 6633

Tel: 07 3356 7034

Vehicle Inspection Report

Shannons

For your information

Process for this report

What is inspected:

This report is based on a visual inspection to the main areas of the vehicle only.

A road test is carried out on the vehicle if roadworthy.

Boxed codes are entered to give an indication on what repairs may be necessary and the level of repair required. It is also an indication of the vehicles overall condition.

We have not removed any part of the vehicle for this inspection.

The underside of vehicle is inspected on a vehicle hoist.

The road test, if conducted, is done within the immediate area of our workshop and done within the local speed limits.

What is not inspected on the vehicle:

Engine compressions

Engine cam/timing belts

Fluid levels and quality of fluid – unless stated elsewhere in this report

Source of oil leaks – unless stated elsewhere in this report

Audio system sound and reception quality

Disclaimer:

L&D Automotive and Shannons, its management, inspectors or staff will not be held liable or responsible for any claim whatsoever in relation to this report and/or to your decision to purchase the vehicle. This report is done on a visual basis only.

We would advise a second opinion on the vehicle if you feel necessary.

L&D Automotive

Kelvin Grove Steering Specialists

David Blee

All mechanical repairs & servicing

Wheel alignment & balancing

Tel: 07 3352 6633

Tel: 07 3356 7034

Report no. 4	
Date 11/10/2021	

Vehicle Make and Model	Jaguar XJ 40
------------------------	--------------

Year	7/1987
VIN	SAJJFALH3AF513809
Odometer – MIs/Km	255082 km
Body Style	4-door convertible saloon
Colour	white/gold

Legend	
<input type="checkbox"/>	Attention required
<input checked="" type="checkbox"/>	In satisfactory order
N/A	Not applicable

Overall Vehicle Condition: Excellent Very good Good **Fair** Poor

Engine/Exhaust:

<input checked="" type="checkbox"/> Engine oil condition	<input checked="" type="checkbox"/> Engine noises	<input checked="" type="checkbox"/> Air filter	<input checked="" type="checkbox"/> Fuel system	<input checked="" type="checkbox"/> Water pump	<input checked="" type="checkbox"/> Exhaust condition
<input checked="" type="checkbox"/> Oil leaks	<input checked="" type="checkbox"/> Engine mounts	<input checked="" type="checkbox"/> Drive belts	<input checked="" type="checkbox"/> Fuel leaks	<input checked="" type="checkbox"/> Radiator/Hoses	<input checked="" type="checkbox"/> Exhaust mounts
<input checked="" type="checkbox"/> Exhaust leaks					

Comments: Engine oil leaks

Transmission/Driveline: Automatic Manual

<input checked="" type="checkbox"/> Transmission	<input checked="" type="checkbox"/> Mounts	<input checked="" type="checkbox"/> Final Drive Unit	<input type="checkbox"/> Clutch OPS N/A	<input checked="" type="checkbox"/> Linkages
<input checked="" type="checkbox"/> Inhibitor Switch	<input checked="" type="checkbox"/> Noises	<input checked="" type="checkbox"/> Driveshaft/Boots	<input checked="" type="checkbox"/> CV/Universal Joints	

Comments: Rear diff oil leaks

Steering/Suspension: Power Assistance: yes no

<input checked="" type="checkbox"/> Steering box/Rack	<input checked="" type="checkbox"/> Steering linkage	<input checked="" type="checkbox"/> Bushes/Pivots	<input checked="" type="checkbox"/> Tyre wear	<input checked="" type="checkbox"/> Driveability
<input checked="" type="checkbox"/> Oil leaks	<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Wheels/Spare	<input checked="" type="checkbox"/> Tyre condition	

Comments: Tyres worn. Less than 10% tread remains.

Front lower control arm bushes worn.

Brakes Hydraulics/ABS:**Electrical:**

<input checked="" type="checkbox"/> Operation	<input checked="" type="checkbox"/> Pads/Lining	<input checked="" type="checkbox"/> Pedal height	<input checked="" type="checkbox"/> Hose condition	<input checked="" type="checkbox"/> Indicators	<input checked="" type="checkbox"/> Horn
<input checked="" type="checkbox"/> Park/Hand brake	<input checked="" type="checkbox"/> Fluid leaks	<input checked="" type="checkbox"/> Pedal rubbers	<input checked="" type="checkbox"/> Headlights	<input checked="" type="checkbox"/> Instrumentation	<input checked="" type="checkbox"/> Exterior lights

Comments: [Horn inoperable.](#)

Body & Miscellaneous:

<input checked="" type="checkbox"/> Window tinting	<input checked="" type="checkbox"/> Panel condition	<input checked="" type="checkbox"/> Heater	<input checked="" type="checkbox"/> Door operation	<input checked="" type="checkbox"/> Door locks
<input checked="" type="checkbox"/> Corrosion	<input checked="" type="checkbox"/> Paint condition	<input checked="" type="checkbox"/> Windscreen	<input checked="" type="checkbox"/> Window operation	<input checked="" type="checkbox"/> Seats and trim
<input checked="" type="checkbox"/> Demister	<input checked="" type="checkbox"/> Air conditioner	<input checked="" type="checkbox"/> Door handles	<input checked="" type="checkbox"/> Seat belts	

Comments: [Left -front radiator support panel rusting.](#)

[Window tint scratched.](#)

[Body changed to convertible.](#)