

Pre-Purchase Inspection

Classic Automobilia

0425 250 613

Maintenance, Modifications & Restorations

Report No

Auction Lot No

130

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
20/10/2021	Ford XM Futura Coupe	1964	53,125mls	D14812

Overall Rating	Comments
★ ★ ★ ★ ☆	Presents well, solid car.

EXTERIOR

Good Fair Repair N/C N/A Comments

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Glass	✓					
Bodywork	✓					
Paintwork	✓					
Lamps Condition	✓					
Bumper Bars	✓					
Brightwork		✓				Bonnet trim and some interior chrome pitted.
Seals			✓			Side window seals U/S.
Convertible Roof					✓	

INTERIOR

Good Fair Repair N/C N/A Comments

	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓					
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim	✓					Centre console lid N/S.
Doors		✓				Driver's door hard to close, door lock knobs N/W (doors lock via keys)
Windows and Mirrors	✓					
Heating and Ventilation			✓			N/W.
Lights/Wipers/Washers/Horn			✓			Indicators do not cancel.
Other Electrical			✓			Interior lamp N/W. Brake light switch not connected.
Entertainment Equipment			✓			N/W.
ABS/SRS					✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					
Corrosion	✓					
Powertrain	✓					
Exhaust			✓			Exhaust manifold leaking.
Brakes			✓			Rear brake hose U/S.
Wheels & Tyres	✓					
Steering & Suspension		✓				Mounting bushes aged and perished. Steering components aged and worn.
Fuel System	✓					
Fluid Leaks		✓				Engine, transmission and final drive leaking.

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation		✓				
Fluid Levels/Condition			✓			Brake fluid dirty.
Cooling System	✓					
Power Steering					✓	
Electrical	✓					
Engine Running			✓			Runs rough and stalls.
Air Conditioning					✓	

ROAD TEST						Comments
	Good	Fair	Repair	N/C	N/A	
Engine Performance		✓				Lacks power.
Transmission			✓			Gear selector alignment not correct.
Noise and Vibration		✓				Underbody noises
Steering and Suspension		✓				
Braking	✓					
Clutch					✓	
Instruments			✓			Speedo, fuel and temp gauges N/W.

General Comments

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked
★ ☆ ☆ ☆ ☆	Vehicle requires substantial work or restoration		
★ ★ ☆ ☆ ☆	Vehicle is in poor condition and in need of TLC		
★ ★ ★ ☆ ☆	Vehicle is commensurate with age and useable		
★ ★ ★ ★ ☆	Vehicle is in very good condition		
★ ★ ★ ★ ★	Vehicle is in excellent condition		

Disclaimer

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.

This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.