



**SANGATE AUTOMOTIVE & SERVICE CO.**

72 Henderson Road,  
Clayton Nth Victoria 3169  
Telephone: (03) 9562 5000  
Facsimile: (03) 9562 5888  
Email: sangateservice@bigpond.com

**Pre-Purchase Inspection Report**

(This report is subject to the conditions on the reverse of this form)

Report No.

H 48

Date

16/08/2019

Legend

A Attention required  
√ In order  
- Not applicable

63

Name  
**Shannons**

Address  
40 CORPORATE DRIVE PHONE: 134646  
HEATHERTON  
VICTORIA, 3202

Vehicle make and model

MERCEDES BENZ 190 SL

Body Style

ROADSTER

Year: CIRCA 1959 Registration: Odometer: 93115 VIN: 1210422000078

Summary of overall condition of vehicle  GOOD  FAIR  POOR

Comments:  
4 CYLINDER TWIN SIDE DRAUGHT SOLEX CARBIE / 4 SPEED MANUAL  
CLEAN, TIDY AND WELL PRESENTED VEHICLE  
DRIVABILITY AND PERFORMANCE TEST GOOD

**Engine/Exhaust**

√ Engine Oil Condition √ Engine Noises √ Air Filter √ Fuel System √ Water Pump √ Exhaust Condition  
A Oil Leaks √ Tune Condition √ Drive Belts √ Fuel Leaks √ Coolant √ Exhaust Mounts  
√ Engine Mounts - Smoke - Emission system √ Radiator/Hoses √ Thermostat √ Exhaust leaks

Comments:

ENGINE OIL LEAK

**Transmission/Driveline**

AUTOMATIC  MANUAL

A Transmission √ Shift Operation √ Noises √ Clutch OPS √ Linkages √ Drive shaft/ Boots  
- Oil/Fluid Condition √ Mounts - Inhibitor Switch √ Adjustment √ CV/Universal joints √ Final Drive

Comments:

GEAR BOX OIL LEAK

**Steering/Suspension**

**Power Assistance**

YES  NO

√ Steering Box/Rack √ Steering linkage √ Shock Absorbers √ Bushes/Pivots √ Tyre Wear √ Wheel/ Spare  
√ Oil Leaks - Power Steering √ Springs √ Wheel Bearings √ Tyre Condition √ Driveability

Comments:

**Brakes**

√ Operation - Pads/lining √ Pedal Height √ Wiring √ Indicators √ Battery  
√ Park brake √ Line Condition √ Pedal Rubbers A Headlights/Aim √ Instrumentation √ Charge Rate  
√ Fluid leaks √ Hose Condition - ABS check light √ Exterior Lighting A Windscreen Wipers √ Horn

Comments:

WINDSCREEN WIPERS OPERATES ON SLOW SPEED AND NOT SELF PARK  
HEADLIGHTS OUT OF FOCUS

**Body**

√ Structure √ Panel condition √ Previous Repairs √ Door/Window op √ Door Locks √ Seat Belts  
A Corrosion √ Paint Condition √ Windscreen/glass √ Windows Tinting √ Seats and Trim √ Door handles

Comments:

MINOR UNDERSIDE SURFACE RUST

**Miscellaneous**

√ Demister - Air conditioner √ Heater - LPG Compliance - Ability to run on Alternative Fuels A Other

Comments:

CABIN CLOCK INOPERATIVE

## **ACCREDITED PREPURCHASE INPECTION REPORT TERMS AND CONDITIONS**

Pre-purchase inspection reports are based on a visual inspection of the condition of the specific items set out in this report form.

Neither Shannons nor Sangate service company pty ltd will be responsible for any defects that could reasonably be expected to have become evident by the dismantling or removal of parts of the vehicle or by inspection of any items not set out in the report form.

Supplementary restraint or air bag systems have been specifically excluded from this test due to the complexity of test procedures. Customers who are considering the purchase of a vehicle fitted with an srs or air bag system are advised to refer the vehicle to an authorized service agent for system functionality.

The pre – purchase inspection report is not substitute for a roadworthy test, which is a tolerance test. The customer acknowledges that receipt of a satisfactory condition report does not mean the vehicle will also pass a roadworthy test.

Sangate will not be held liable for

- a) Carrying out pre-purchase or any services connected with such inspections: or
- b) Providing to any person any information in connection with a pre-purchase vehicle inspection including this report form.

To the extent permissible under the Trade Practices Act and any other act of Parliament, the liability of Sangate for any loss or damage to the vehicle for:

- a) Any breach of any term, condition or warranty implied by such legislation shall be limited to the supply of the service and shall be equivalent to the cost if having the service supplied; and
- b) Any breach of contract or statute or any tort by Sangate shall be limited to an amount equal to the pre- purchase inspection fee paid.