



SANGATE AUTOMOTIVE & SERVICE CO.

72 Henderson Road,
Clayton Nth Victoria 3169
Telephone: (03) 9562 5000
Facsimile: (03) 9562 5888
Email: sangateservice@bigpond.com

Pre-Purchase Inspection Report

(This report is subject to the conditions on the reverse of this form)

Report No.

H 32

Date

3/08/2019

Legend

A Attention required
√ In order
- Not applicable

19

Name
Shannons

Address
40 CORPORATE DRIVE PHONE: 134646
HEATHERTON
VICTORIA, 3202

Vehicle make and model

BENTLEY MK IV

Body Style

SALOON

Year

1951

Registration

Odometer

77882 ML

VIN

B84LJ FROM I/D PLATE

Summary of overall condition of vehicle

GOOD

FAIR

POOR

Comments:

6 CYLINDER TWIN CARBIE/ 4 SPEED CHAUFFER SHIFT
CLEAN AND TIDY VEHICLE
DRIVABILITY AND PERFORMANCE TEST OK

Engine/Exhaust

<input checked="" type="checkbox"/> Engine Oil Condition	<input checked="" type="checkbox"/> Engine Noises	<input checked="" type="checkbox"/> Air Filter	<input checked="" type="checkbox"/> Fuel System	<input checked="" type="checkbox"/> Water Pump	<input checked="" type="checkbox"/> Exhaust Condition
A Oil Leaks	A Tune Condition	<input checked="" type="checkbox"/> Drive Belts	<input checked="" type="checkbox"/> Fuel Leaks	<input checked="" type="checkbox"/> Coolant	<input checked="" type="checkbox"/> Exhaust Mounts
<input checked="" type="checkbox"/> Engine Mounts	- Smoke	- Emission system	<input checked="" type="checkbox"/> Radiator/Hoses	<input checked="" type="checkbox"/> Thermostat	A Exhaust leaks

Comments:

ENGINE OIL LEAK. ENGINE TAILPIPE LEAK
ENGINE IDLE ROUGH AND ENGINE MISFIRE

Transmission/Driveline

AUTOMATIC

MANUAL

<input checked="" type="checkbox"/> Transmission	<input checked="" type="checkbox"/> Shift Operation	<input checked="" type="checkbox"/> Noises	<input checked="" type="checkbox"/> Clutch OPS	<input checked="" type="checkbox"/> Linkages	<input checked="" type="checkbox"/> Drive shaft/ Boots
- Oil/Fluid Condition	<input checked="" type="checkbox"/> Mounts	- Inhibitor Switch	<input checked="" type="checkbox"/> Adjustment	<input checked="" type="checkbox"/> CV/Universal joints	A Final Drive

Comments:

DIFFERENTIAL OIL LEAK

Steering/Suspension

Power Assistance

YES

NO

<input checked="" type="checkbox"/> Steering Box/Rack	<input checked="" type="checkbox"/> Steering linkage	<input checked="" type="checkbox"/> Shock Absorbers	<input checked="" type="checkbox"/> Bushes/Pivots	<input checked="" type="checkbox"/> Tyre Wear	<input checked="" type="checkbox"/> Wheel/ Spare
<input checked="" type="checkbox"/> Oil Leaks	- Power Steering	<input checked="" type="checkbox"/> Springs	<input checked="" type="checkbox"/> Wheel Bearings	<input checked="" type="checkbox"/> Tyre Condition	<input checked="" type="checkbox"/> Driveability

Comments:

Brakes

<input checked="" type="checkbox"/> Operation	- Pads/lining	<input checked="" type="checkbox"/> Pedal Height	<input checked="" type="checkbox"/> Wiring	<input checked="" type="checkbox"/> Indicators	<input checked="" type="checkbox"/> Battery
A Park brake	<input checked="" type="checkbox"/> Line Condition	<input checked="" type="checkbox"/> Pedal Rubbers	<input checked="" type="checkbox"/> Headlights/Aim	<input checked="" type="checkbox"/> Instrumentation	<input checked="" type="checkbox"/> Charge Rate
<input checked="" type="checkbox"/> Fluid leaks	<input checked="" type="checkbox"/> Hose Condition	- ABS check light	<input checked="" type="checkbox"/> Exterior Lighting	<input checked="" type="checkbox"/> Windscreen Wipers	<input checked="" type="checkbox"/> Horn

Comments:

PARK BRAKE NEEDS ATTENTION TOWARDS OPERATION

Body

<input checked="" type="checkbox"/> Structure	<input checked="" type="checkbox"/> Panel condition	<input checked="" type="checkbox"/> Previous Repairs	<input checked="" type="checkbox"/> Door/Window op	<input checked="" type="checkbox"/> Door Locks	- Seat Belts
A Corrosion	A Paint Condition	<input checked="" type="checkbox"/> Windscreen/glass	<input checked="" type="checkbox"/> Windows Tinting	A Seats and Trim	<input checked="" type="checkbox"/> Door handles

Comments:

ORIGINAL INTERIOR HAS VARIOUS WEAR AND DEFECTS - DRIVERS SEAT REUPHOLSTERED SEAT
ADJUSTMENT INOPERATIVE. VARIOUS MINOR PAINT DEFECTS
VARIOUS UNDERSIDE SURFACE RUST

Miscellaneous

- Demister	- Air conditioner	- Heater	- LPG Compliance	- Ability to run on Alternative Fuels	A Other
------------	-------------------	----------	------------------	---------------------------------------	---------

Comments:

CABIN CLOCK INOPERATIVE

ACCREDITED PREPURCHASE INPECTION REPORT TERMS AND CONDITIONS

Pre-purchase inspection reports are based on a visual inspection of the condition of the specific items set out in this report form.

Neither Shannons nor Sangate service company pty ltd will be responsible for any defects that could reasonably be expected to have become evident by the dismantling or removal of parts of the vehicle or by inspection of any items not set out in the report form.

Supplementary restraint or air bag systems have been specifically excluded from this test due to the complexity of test procedures. Customers who are considering the purchase of a vehicle fitted with an srs or air bag system are advised to refer the vehicle to an authorized service agent for system functionality.

The pre – purchase inspection report is not substitute for a roadworthy test, which is a tolerance test. The customer acknowledges that receipt of a satisfactory condition report does not mean the vehicle will also pass a roadworthy test.

Sangate will not be held liable for

- a) Carrying out pre-purchase or any services connected with such inspections: or
- b) Providing to any person any information in connection with a pre-purchase vehicle inspection including this report form.

To the extent permissible under the Trade Practices Act and any other act of Parliament, the liability of Sangate for any loss or damage to the vehicle for:

- a) Any breach of any term, condition or warranty implied by such legislation shall be limited to the supply of the service and shall be equivalent to the cost if having the service supplied; and
- b) Any breach of contract or statute or any tort by Sangate shall be limited to an amount equal to the pre- purchase inspection fee paid.