

Pre Purchase Inspection Report

(this report is subject to the terms and conditions on the reverse of this form)

Name SHANNONS		Phone 	Legend Needs attention = A In order = ✓ Not applicable = na	Stock No.
Address CORPORATE DRIVE MOORABBIN				Date 6/07/2021
Vehicle make and model HOLDEN COMMODORE HSV GTS BLACK				Report No. 42
Year 1995	Registration NO REG	Odometer 91459		VIN VS8VK19-XY2
Overall condition of vehicle		Good	✓ Fair	Poor

Comments:

Engine/Exhaust

✓ Oil condition	✓ Engine noise	✓ Air filter	✓ Fuel system	✓ Water pump	✓ Exhaust condition
✓ Oil leaks	✓ Tune condition	✓ Drive belts	✓ Fuel leaks	✓ Coolant	✓ Exhaust mounts
✓ Engine mounts	✓ Smoke	✓ Emission system	✓ Radiator/hoses	✓ Thermostat	✓ Exhaust leaks

Comments:

Transmission/Driveline

Automatic		✓ Transmission	✓ Shift operation	✓ Noise	✓ Clutch operation	✓ Linkages	✓ Drive shaft boots
✓ Oil/fluid condition	✓ Mounts	✓ Inhibitor switch	✓ Adjustments	✓ CV/universal joints	✓ Final drive		

Comments:

Steering/Suspension

✓ Steering box/rack	✓ Steering linkage	✓ Shock Absorbers	✓ Bushes/pivots	✓ Tyre wear	✓ Wheel/spare
✓ Oil leaks	✓ Power steering	✓ Springs	✓ Wheel bearings	✓ Tyre condition	✓ Driveability

Comments:

Brakes

✓ Operation	✓ Pads/linings	✓ Pedal feel	✓ Wiring	✓ Indicators	✓ Battery
✓ Park brake	✓ Line condition	✓ Pedal rubbers	✓ Headlights/aim	✓ Instrumentation	✓ Charge rate
✓ Fluid leaks	✓ Hose condition	na ABS check light	✓ Exterior lighting	✓ Windscreen wipers	✓ Horn

Comments:

Body

✓ Structure	✓ Panel condition	✓ Previous repairs	✓ Door/window ops	✓ Door locks	✓ Seat belts
✓ Corrosion	✓ Paint condition	✓ Windscreen/glass	✓ Window tint	✓ Seats/trim	✓ Door handles

Comments:

Miscellaneous

✓ Demister	✓ Air conditioner	✓ Heater	na LPG compliance	na LPG running	na Other
na Convertalbe top - Condition		na Convertible top - operation			

Comments:

DRIVES VERY GOOD

Vehicle Inspection Disclaimer

This vehicle inspection report is based on largely a visual inspection. It is not practical to dismantle every item on the vehicle for inspection.

This inspection is prepared for Shannons Auctions and no warranty is offered or provided, nor is equivalent or a substitute of a roadworthy certificate. The report may indicate a problem or problems but not provide any further details into the problem this is because further dismantling may be required to provide accurate diagnosis. Whilst every care is taken, EuroCars Road & Track Pty Ltd cannot report on a defect that the inspector cannot see or does not appear during inspection.

EuroCars Road & Track or Shannons will not be held responsible for defects that may have been disguised in order to deceive the agent/s or potential buyers.

EuroCars Road & Track do not check every item, items that are excluded (but not limited to) include; timing belts / chains, security system, entertainment systems including cassette/compact disc players, etc.

We do not take any responsibility for the verification or authentication of the vehicle; this is solely the responsibility of the purchaser. VIN, Chassis and Engine numbers are checked however not guaranteed.

It is recommended to refer any vehicle with a supplementary restraint or air bag system to an authorised agent for inspection. EuroCars will not be held liable for any change in condition or damage after initial inspection.